CITY OF KIRKLAND
123 5th Avenue
Kirkland, WA 98033
www.kirklandpermits.net

DO NOT REMOVE
MECHANICAL ~~ELECTRICAL~~ INSPECTION CORRECTION REPORT

INSPECTION REQUEST LINE ~~(425) 587-3225~~ Request must be made prior to 7pm for next day inspection. The corrections listed below are hereby ordered and must be completed within **15 days.** Refer to National Electrical Code or State Rules for Safety Standards.

DATE: 1 / 20 / 15

OWNER / CONTRACTOR: APOPEI

PERMIT NUMBER: MSF14-0046

ADDRESS: 5555 116TH AVE NE

☐ NOT APPROVED FOR COVER ☐ NOT APPROVED FOR SERVICE

SAFETY DEFECTS NEEDING CORRECTION

1. AS PER CORRECTION DATED 10-17-14 OUTSIDE AIR DUCTING REQUIRES MOTORIZED DAMPER INTERLOCKED WITH LAUNDRY EXHAUST + HVAC OPERATIONS.

2. OUTSIDE AIR DUCT IS NOT CONNECTED TO HVAC UNIT (LAYING ON GROUND UNDER HOUSE)

3. BLOWER DOOR TEST + ENERGY STICKER REQUIRED FOR ADDITION

NOTIFY INSPECTION OFFICE WHEN READY FOR REINSPECTION

MIKE MCGIVERN
INSPECTOR